## **Under Review Notification**

Raised By: VANESSA MOREL Product #: DART TOOLING EUROCOPTER

Date: 17.12.05 Product Name: HYDRAULIC PUMP SEAL EXCHANGE

		"Y" or "N" Required for Each Part Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")	Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBEM632V3010101-3	RBEM632V3010101 REV 1	Ν	Ν	Ν	Ν	Υ	Υ	Υ	17-779	FIT ISSUE
RBEM632V3010101-5	RBEM632V3010101 REV 1	Ν	Ν	Ν	Ν	Ν	Υ	Υ	17-779	PRODUCTION ISSUE

Description of Issue:

FIT ISSUE

RBEM632V3010101-3: GD&T TOLERANCE ADDED FOR COCENTRICITY ALIGMENT

RBEM632V3010101-5: STOCK BOLT CHANGED FOR CUSTOM BOLT DUE TO PRODUCTION ISSUE / DEVIATION NEED TO BE SIGN

Distribution:

VP Operations
Director of Operations
Director Quality Assurance
Director of Engineering

Chief Engineer
Engineering Project Managers
Engineering Clerk
Customer Support Manager

Production Engineers
Production Planners
Purchasing Manager
Technical Support

Product Manager - Solutions Provider